

**Buchner 2-2H Photographs**  
**Inspection Doc # 696303726**  
**Loc ID 431634**  
**API No. 123-36703**



Stained soil at wellhead removed



Stained soil east of gearbox removed



Stained soil west of gearbox removed



Stained soil at exhaust removed



Stained soil at gas engine removed