

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402866100

Date Received:  
11/09/2021

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Hartman, Laura</u>		<u>lhartman@blm.gov</u>
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>
<u>Jones, Tammy</u>		<u>tajones@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903770  
Inspection Date: 10/19/2021 FIR Submit Date: 10/21/2021 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326232

Location Name: HUBER/SPC -FEDERAL- Number: 13NESW County: LA PLATA  
N35N8W  
Qtrqtr: NESW Sec: 13 Twp: 35N Range: 8W Meridian: N  
Latitude: 37.300230 Longitude: -107.699050

FACILITY - API Number: 05-067- -00 Facility ID: 216077

Facility Name: HUBER/SPC -FEDERAL Number: 2-13  
Qtrqtr: NESW Sec: 13 Twp: 35N Range: 8W Meridian: N  
Latitude: 37.300230 Longitude: -107.699050

CORRECTIVE ACTIONS:

1 CA# 157036

Corrective Action: -All equipment needs to be removed. This includes any inactive flowlines or risers not abandoned that serviced the well.  
-Weeds need to be controlled.  
-Well pad and access road need to be reclaimed to COGCC reclamation standards per 1000 series reclamation rules.

Date: 07/01/2021

Response: CA COMPLETED

Date of Completion: 11/09/2021

Operator Comment: Equipment and road are still active and in use, and unable to be removed and reclaimed. This equipment and road are associated with the pipeline and right-of-way that goes through this P&A'd location. The pipeline has a low point that services the Huber Arado 1-13.

Musk thistles, Canadian thistles and other weeds have been removed and erosion control has been installed on slope.

COGCC Decision: \_\_\_\_\_

COGCC Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: \_\_\_\_\_

Title: OperationsRegulatory Tech

Date: 11/9/2021 12:31:46 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number      Description**

402866112	Huber SPC Federal 2-13_Resolved Photos
-----------	--

Total Attach: 1 Files