

Today's Date:	10/21/2021					
Well Name:	HUBER/SPC -FEDERAL 2-13	Location:	Sec: 13	Twn: 035N	Rng: 008W	UL: K
API Number:	05.067.07683	Footage:				
Operator:	Hilcorp Energy Company	Area/Run/MSO:	01	0100	Charlie Ruybal	
Meter #:			Pipeline:			
INC Number:	693903770	Agency:	COGCC	Inspector:	Catherine Roy	
Type of INC:	Written	Photos Required:	Yes	Due Date:	7/1/2021	
Issue of Concern:	<p>Comment: Unused equipment remains within the project area. Flowline markers observed. Well pad and access road are not recontoured and reclaimed. Thousands of musk thistles and Canada thistles observed within the eastern project area.</p> <p>-All equipment needs to be removed. This includes any inactive flowlines or risers not abandoned that serviced the well.</p> <p>-Weeds need to be controlled.</p> <p>-Well pad and access road need to be reclaimed to COGCC reclamation standards per 1000 series reclamation rules.</p>					

1-970-247-7708
 HUBER/SPC FED #2-13
 1850' FWL 1820' FSL
 E/SW SEC 13K T35N R08W
 LATITUDE 37° 17' 59.3514" N
 LONGITUDE 107° 41' 54.24" W
 API# 05-067-07683
 LEASE # COC-46245
 CA# COC-543502
 LA PLATA COUNTY, COLORADO

Equipment and road are still active and in use, and unable to be removed and reclaimed. This equipment and road are associated with the pipe line and right-of-way that goes through this P&A'd location.

Musk thistles, Canadian thistles and other weeds have been removed and erosion control has been installed on slope.

