

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/03/2021

Submitted Date:

11/03/2021

Document Number:

693505747**FIELD INSPECTION FORM**Loc ID 426843 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------|---------------------------------|
| , | | cogccinspection@pdce.com | ALL INSPECTIONS |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 426796 | WELL | PR | 01/01/2020 | OW | 123-34782 | NC Farms 16-32 | PR |
| 426806 | WELL | PR | 05/01/2019 | OW | 123-34785 | NC Farms 10-32 | PR |
| 426816 | WELL | PR | 05/01/2019 | OW | 123-34789 | NC Farms 15-32 | PR |
| 426819 | WELL | PR | 05/01/2019 | OW | 123-34790 | NC Farms 9-32 | PR |
| 426823 | WELL | PR | 05/01/2019 | OW | 123-34793 | NC Farms 20-32 | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|--|--|------------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Sign not posted or information inaccurate at 16-32 well head | | |
| Corrective Action: | Install sign to comply with Rule 605.d. | | Date: 12/03/2021 |
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | | Date: |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|--|------------------|
| Type | OTHER | | |
| Comment: | Stained soil around compressor skid | | |
| Corrective Action: | Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906 | | Date: 12/03/2021 |
| Type | OTHER | | |
| Comment: | Mechanical issue; Kim Ray valve appears to be leaking and equipment on compressor skid | | |
| Corrective Action: | Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. | | Date: 12/03/2021 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|-------------------------------|-----|--|-----------------|
| | | | corrective date |
| Type: Bradenhead | # 5 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Emission Control Device | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 5 | | |
| Comment: | | | |

| | | | |
|-----------------------------------|-----|-------|--|
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Compressor | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 1 | 100 BBLs | PBV FIBERGLASS | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|---|---------------------|---------------------|-------------|
| | | | | |
| Comment: | Shares containment with crude oil tanks | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 2 | 300 BBLs | STEEL AST | | 40.522576,-104.568036 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |

| Inspected Facilities | | | |
|---|------------|------------------------------|----------------------------------|
| Facility ID: 426796 | Type: WELL | API Number: 123-34782 | Status: PR Insp. Status: PR |
| <u>Producing Well</u> | | | |
| Comment: PR | | | |
| Corrective Action: | | Date: | |
| <u>BradenHead</u> | | | |
| Date of Last Brhd Test: 04/16/2020 | | Annual Brhd Completed? No | |
| Last Brhd Test Results | | Initial Surf Csg Pressure: 0 | Fluid Type: |
| | | End Surf Csg Pressure: 0 | |
| Comment: Submit reports | | | |
| Corrective Action: | | Date: | |
| Facility ID: 426806 | Type: WELL | API Number: 123-34785 | Status: PR Insp. Status: PR |
| <u>Producing Well</u> | | | |
| Comment: PR | | | |
| Corrective Action: | | Date: | |
| <u>BradenHead</u> | | | |
| Date of Last Brhd Test: 04/16/2020 | | Annual Brhd Completed? No | |
| Last Brhd Test Results | | Initial Surf Csg Pressure: 0 | Fluid Type: |
| | | End Surf Csg Pressure: 0 | |
| Comment: Submit reports | | | |
| Corrective Action: | | Date: | |
| Facility ID: 426816 | Type: WELL | API Number: 123-34789 | Status: PR Insp. Status: PR |
| <u>Producing Well</u> | | | |
| Comment: PR | | | |
| Corrective Action: | | Date: | |
| <u>BradenHead</u> | | | |
| Date of Last Brhd Test: 04/16/2020 | | Annual Brhd Completed? No | |
| Last Brhd Test Results | | Initial Surf Csg Pressure: 9 | Fluid Type: |
| | | End Surf Csg Pressure: 9 | |
| Comment: Submit reports | | | |
| Corrective Action: | | Date: | |
| Facility ID: 426819 | Type: WELL | API Number: 123-34790 | Status: PR Insp. Status: PR |
| <u>Producing Well</u> | | | |
| Comment: PR | | | |
| Corrective Action: | | Date: | |

BradenHead

Date of Last Brhd Test: 04/16/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment: [Submit reports](#)

Corrective Action:

Date:

Facility ID: 426823 Type: WELL API Number: 123-34793 Status: PR Insp. Status: PR

Producing WellComment: [PR](#)

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/16/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment: [Submit reports.](#)

Corrective Action:

Date:

COGCC Comments

| Comment | User | Date |
|--|---------|------------|
| <p>COGCC Inspection Report Summary On Wednesday November 3, 2021 at approximately 1:15PM, I Inspector Randy Silver, conducted an on-site inspection. Location: NC Farms 16-32 Operator: PDC Energy API#: 123-34782 County: Weld While there, I observed PR well site and production facility During this inspection the following possible compliance issues were observed: Well sign: Rule 605 d Corrective action date of 12-3-21 See photo 1 Mechanical issue: Rule 608 e Corrective action date of 12-3-21 see photo 5 Stained soil: Rule 906 Corrective action date of 12-3-21 See photo 6 Weather conditions: Clear A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> | silverr | 11/03/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402861384 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5571348 |
| 693505748 | loc pic | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5571337 |