

Inspection Photos
Operator: Logos
API: 067-05591
Date: 11/3/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Vegetation is in a grazed vegetative condition. Inset shows a grazed bunchgrass (likely Indian ricegrass) next to boot.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of reference area comprised of open pasture with grasses and forbs largely in a grazed condition at this time.