

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/01/2021

Submitted Date:

11/04/2021

Document Number:

696203338**FIELD INSPECTION FORM**Loc ID 335889 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1001 17TH STREET #1900City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Arthur, Denise		denise.arthur@state.co.us	
,		dnr_cogccenforcement@state.co.us	
, Laramie		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335889	LOCATION	AC			-	Cascade Creek 697-09-61	RI

General Comment:

On 11/1/2021, Reclamation Specialist Trujillo inspected Laramie Energy LLCs' Cascade Creek 697-09-61 Location in Garfield County, Colorado.

This inspection is a followup to:

#696201787 dated 9/16/2020;

#696201980 dated 11/2/2020;

#696202122 dated 12/8/2020;

#696202928 dated 7/12/2021;

#696203107 dated 8/23/2021;

and #696203152 dated 9/8/2021 to document compliance with the following corrective actions on the Location:

-1002.f: Stormwater

-606.c: Undesirable (noxious) plant species

This inspection is also in response to NOAV #402812356 issued 9/15/2021.

This inspection is solely for the Location and does not resolve any outstanding corrective actions associated with the Remediation Project #4620.

Refer to the "Location" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	<p>Previous inspections observed Undesirable (Noxious) plant species on the interim areas of the Location. Inspection required Operator to comply with Rule 606.c</p> <p>Noxious weeds not observed during inspection; corrective action appears to have been addressed.</p> <p>Continue to monitor and manage Undesirable Plant Species on the Location to prevent further spread and establishment. A followup inspection will be conducted in a future growing season to document compliance with Rule 606.c.</p>		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [See "COGCC Comments" for comments regarding Stormwater](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C. Ensure control measures are adequate for the site's conditions, installed in accordance with good engineering practices, and maintained in proper functioning condition](#)

Date: 10/02/2020

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>STORMWATER COMMENT</p> <p>Previous inspections observed that Operator implemented erosion control blankets on the slopes of the north and west end of the Location; however, control measures to protect and stabilize a large section of cut slope remained missing or insufficient; inspections documented that corrective actions requiring compliance with Rule 1002.f were not addressed, and remain applicable.</p> <p>It was observed in this inspection that stabilization of the cut slope on the Location remains inadequate; control measures to protect, and stabilize the slopes remain missing or insufficient; erosion degradation evident.</p> <p>Erosion control blanket directly west of the unstabilized slope has not been maintained in proper functioning condition.</p> <p>Corrective actions have not been addressed and remain applicable.</p>	trujilloam	11/04/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402862661	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5572639
696203341	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5572629