

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402868987

Date Received:  
11/12/2021

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46685  
Name of Operator: KINDER MORGAN CO2 CO LP  
Address: 1001 LOUISIANA ST SUITE 1000  
City: HOUSTON State: TX Zip: 77002  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Michael Hannigan	970-882-5532	michael_hannigan@kindermorgan.com
_General		CO2Source_Regulatory@kindermorgan.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903730  
Inspection Date: 10/11/2021 FIR Submit Date: 10/13/2021 FIR Status:

Inspected Operator Information:

Company Name: KINDER MORGAN CO2 CO LP Company Number: 46685  
Address: 1001 LOUISIANA ST SUITE 1000  
City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 322104

Location Name: DOE CANYON UT 19-40-17-N40N17W Number: 19NENE County: DOLORES  
Qtrqtr: NENE Sec: 19 Twp: 40N Range: 17W Meridian: N  
Latitude: 37.719443 Longitude: -108.757903

FACILITY - API Number: 05-033-00 Facility ID: 208973

Facility Name: DWD Number: 1  
Qtrqtr: NENE Sec: 19 Twp: 40N Range: 17W Meridian: N  
Latitude: 37.719443 Longitude: -108.757903

CORRECTIVE ACTIONS:

1 CA# 156831

Corrective Action: Operator needs to assess cut-slope and reduce as described in variance request condition of approval. Corrective action is back-dated to date that variance was approved to document duration of non-compliance.

Date: 06/20/2019

Response: CA COMPLETED

Date of Completion: 11/12/2021

Operator Comment: A surveyor collected topographic data from the slopes located on the north and east sides of the DWD-1 final reclamation area. The survey data show that the reclaimed slopes vary between 3.8 (horizontal) to 1.0 (vertical) and 8.0 (horizontal) to 1.0 (vertical). The reclamation standard is that slopes should be no steeper than 3.0

(horizontal) to 1.0 (vertical) and the survey data validate that all slopes are shallower than the standard. The survey data, with notes giving the slope sections in H:V values, is attached.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: A surveyor collected topographic data from the slopes located on the north and east sides of the DWD-1 final reclamation area. The survey data show that the reclaimed slopes vary between 3.8 (horizontal) to 1.0 (vertical) and 8.0 (horizontal) to 1.0 (vertical). The reclamation standard is that slopes should be no steeper than 3.0 (horizontal) to 1.0 (vertical) and the survey data validate that all slopes are shallower than the standard. The survey data, with notes giving the slope sections in H:V values, is attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Hannigan

Signed: \_\_\_\_\_

Title: EHS Supervisor

Date: 11/12/2021 7:00:29 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
402868989	DWD-1 Slope Survey Data

Total Attach: 1 Files