

Inspection Photos
Operator: Simcoe
API: 067-06969
Date: 11/8/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with rubber rabbitbrush, western wheatgrass, and sand dropseed.



Photo 3. View of the northern project area from the northeastern corner facing westward. Flowline excavation is occurring in the northern project area.



Photo 4. View of reference area comprised of open grass field with western wheatgrass, smooth brome, and scattered sagebrush.