

Inspection Photos
Operator: Simcoe
API: 067-08758
Date: 11/8/2021



Photo 1. View of the project area from the well pad entrance facing center. Debris observed during previous inspection is not observed.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with rubber rabbitbrush, western wheatgrass, and smooth brome.



Photo 3. View of reference area comprised of open grass field with western wheatgrass, smooth brome, and thickspike wheatgrass.