

Inspection Photos  
Operator: Simcoe  
API: 067-08707  
Date: 11/8/2021



Photo 1. View of the project area from the well pad entrance facing center.





Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with crested wheatgrass, western wheagrass, and sand dropseed. Weeds observed in July 2021 inspection not observed.





Photo 3. View of the eastern project area from the southeastern corner facing northward.





Photo 4. View of reference area comprised of pinyon and juniper woodland with blue grama, prickly pear, and black sagebrush in the understory.