

Inspection Photos
Location Name: Wildhorse 18-1834H
Location ID: 430306



Colorado Oil and Gas Conservation Commission
40.75759, -104.01826, 4967.3ft, 204'
11/10/2021 13:57:17



Colorado Oil and Gas Conservation Commission
40.75698, -104.01891, 4948.9ft, 106'
11/10/2021 13:57:54

Photo 1 – Sign at Entrance

Photo 2 – Wellhead – Weeds

Inspection Photos
Location Name: Wildhorse 18-1834H
Location ID: 430306



Colorado Oil and Gas Conservation Commission
40.75696, -104.01866, 4966.2ft, 355°
11/10/2021 13:58:23



Colorado Oil and Gas Conservation Commission
40.75697, -104.01864, 4953.9ft, 306°
11/10/2021 13:58:45

Photo 3 – Stained Soil at Gas Engine

Photo 4 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Wildhorse 18-1834H
Location ID: 430306



Colorado Oil and Gas Conservation Commission
40.75696, -104.01865, 4955.3ft, 281°
11/10/2021 13:58:52



Colorado Oil and Gas Conservation Commission
40.75694, -104.01864, 4962.4ft, 295°
11/10/2021 13:59:10

Photo 5 – Oily Waste

Photo 6 – Stained Soil at Exhaust

Inspection Photos
Location Name: Wildhorse 18-1834H
Location ID: 430306



Photo 7 – Weeds in I.R. Area

Photo 8 – Weeds in I.R. Area

Inspection Photos
Location Name: Wildhorse 18-1834H
Location ID: 430306



Photo 9 – Weeds in I.R. Area

Photo 10 – Weeds in I.R. Area

Inspection Photos
Location Name: Wildhorse 18-1834H
Location ID: 430306



Photo 11 – Weeds in I.R. Area

Photo 12 – Weeds in I.R. Area