

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/10/2021

Submitted Date:

11/11/2021

Document Number:

701102196

**FIELD INSPECTION FORM**Loc ID 315047 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 74290

Name of Operator: RETAMCO OPERATING INC

Address: PO BOX 790

City: RED LODGE State: MT Zip: 59068

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gose, Tom	210-216-0819	tomgose@retamco.com	
Johnson, Joe	406-446-1568	JoeJohnson@retamco.com	
Thompson, Bud		BLThomps@BLM.gov	
Glennon, Joe	406-446-1568	joeglennon@retamco.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230164	WELL	PR	06/01/2021	GW	103-07823	PHILADELPHIA CREEK 7	PR

**General Comment:**

COGCC Follow Up Inspection Report Summary  
Follow up to 09/07/2021 inspection # 701101924

Uncorrected action item(s)

- No battery sign at tank battery
- No capacity volume on label.

Corrected action item(s)

- Weeds were addressed
- Thief hatch is closed.

During this inspection the following compliance issues were observed:

- Tank label as WATER with NFPA diamond RED4 BLUE 2 YELLOW 1

Contents posted as "Water" Water is not a proper content name for fluids recovered from down hole of well.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	No battery sign at tank battery.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	12/08/2021
Type	TANK LABELS/PLACARDS		
Comment:	No capacity volume on label.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	12/08/2021
Type	TANK LABELS/PLACARDS		
Comment:	Tank label as WATER with NFPA diamond RED4 BLUE 2 YELLOW 1 Contents posted as "Water" Water is not a proper content name for fluids recovered from down hole of well.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	12/31/2021

**Emergency Contact Number:**

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds were addressed		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
	1	100 BBLS	STEEL AST		,	
Comment:	Thief hatch is closed.					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Earth					
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 230164 Type: WELL API Number: 103-07823 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701102200	Inspection 701102196 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5579940">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5579940</a>