



Mesa 43-20



Cattleguard was cleaned of sediment and reseeded



Reseeded disturbed areas



Cleaned drilling mud up per Rule 902.b.



Repaired areas of vehicle tracks and rutting to comply with rule 1002.e.



Repaired areas of vehicle tracks and rutting to comply with rule 1002.e.



Repaired areas of vehicle tracks and rutting to comply with rule 1002.e. Reseeded disturbed areas

Reseeded disturbed areas



Repaired areas of vehicle tracks and rutting to comply with rule 1002.e. Reseeded disturbed areas
Installed or repaired required BMPs per Rule 1002.f.(2)C