

Final Reclamation Inspection

November 8, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 305716

Inspection Document #: 697503480

Weld County, CO

NWSE Section 21 T2N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GERKIN-62N64W /21NWSE
Location ID: 305716



Photo 1. Photo taken from the gate and fencing that was a previous complaint, South. Photo illustrates that complaint item has been completed and no further action required.



Inspection Photos
Location Name: GERKIN-62N64W /21NWSE
Location ID: 305716



Photo 2. Photo taken from the northern well location, facing South. Photo illustrates germination of desirable plant species along the eastern location but most of the well location consists of Kochia.



Photo 3. Photo taken from the eastern well location, facing South. See comments under Photo 2.

Inspection Photos
Location Name: GERKIN-62N64W /21NWSE
Location ID: 305716



Photo 4. Photo taken from the northern well location, facing Southwest. Photo illustrates the well location (red arrow putting at Kochia) and reference area (yellow arrows pointing at the reference area).



Photo 5. Photo taken from a portion of the well location. Photo illustrates a List B Colorado noxious weed, Canada thistle. Canada thistle rosettes were observed sparratically in areas of the location.

Inspection Photos
Location Name: GERKIN-62N64W /21NWSE
Location ID: 305716



Photo 6. Photo taken from the well location, facing East. Photo illustrates a portion of the access road is now part of a livestock grazing area. The tank battery and remainder of the access road are beyond the gate illustrated in the photo.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697503480

Inspection Photos
Location Name: GERKIN-62N64W /21NWSE
Location ID: 305716



Photo 7. Photo taken from the eastern access road, facing South. Photo illustrates weeds throughout the entire eastern access road with no desirable establishment observed.



Photo 8. Photo taken from the tank battery, facing West. See comments under Photo 7.