



- Photo 1 –



- Photo 2 –



- Photo 3 – Wellhead oil leak



- Photo 4 –



- Photo 5 – Produced water pits not maintaining a minimum of 2 feet of freeboard



- Photo 6 – Secondary containment around oil skim tank needs improvement



- Photo 7 – Secondary containment around oil skim tank needs improvement



- Photo 8 – Secondary containment around oil skim tank needs improvement



- Photo 9 – Produced water pit not maintaining 2 feet of freeboard, no method to monitor freeboard



- Photo 10 – Produced water pit not maintaining 2 feet of freeboard, no method to monitor freeboard



- Photo 11 – Reclamation south of produced water pit is not adequate



- Photo 12 – BMPs are required south of the produced water pits to prevent offsite sediment migration



- Photo 13 – Reclamation south of produced water pit is not adequate



- Photo 14 – Produced water pit not maintaining 2 feet of freeboard



- Photo 15 – Channel cutting to lower (eastern) PW pit. Fluid level control is not adequate



- Photo 16 – Equalization siphon pipe is not performing adequately