

Inspection Photos
Location Name: Dorris Ackerson Unit #2
Location ID: 318223



Photo 1 loc pic



Photo 2 Dead weeds around electric panel and location.

Inspection Photos
Location Name: Dorris Ackerson Unit #2
Location ID: 318223



Photo 3 well head sign not readable



Photo 4 Dead weed around location.