

Stormwater Inspection

November 11, 2021

Operator: K P KAUFFMAN COMPANY INC - 46290

Location ID: 480127

Inspection Document #: 697503504

Weld County, CO

NWNW Section 9 T1N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: RMF Consolidation Line
Location ID: 480127



Measure Distance

Click a start and end point.

Measure units:

Miles

Segment: 71.19 (Feet)

Segment: 0.01 (Miles)

Total: 71.19 (Feet)

Total: 0.01 (Miles)

- To measure multiple distances, continue clicking new points.
- To finish, click "Stop".
- For reference, feet are always displayed above selected unit of measurement.
- You can pan or zoom and continue measuring by clicking "Resume".
- To start over, click "Clear".

Clear

Stop

Photo 1. COGCC GISOnline 2019 aerial imagery illustrates the open remediation is approximately 70' from Little Dry Creek. Little Dry Creek is downgradient from the remediation.

Inspection Photos
Location Name: RMF Consolidation Line
Location ID: 480127



Photo 2. Photo taken from the remediation project, facing Northwest. Photo illustrates unmanaged run-on erosion into an open excavation with no outlet projection.

Inspection Photos
Location Name: RMF Consolidation Line
Location ID: 480127



Photo 3. Photo taken from the outlet/discharge point, facing North. Photo illustrates Operator has failed to install any type of stormwater BMP.

Inspection Photos
Location Name: RMF Consolidation Line
Location ID: 480127



Photo 4. Photo taken from the remediation project, facing Southeast. See comments under Photo 2. Photo also illustrates an inadequate fence to prevent access when site is not attended.



Photo 5. Photo taken from the remediation project, facing North. See comments under Photo 4.