

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2021

Submitted Date:

11/16/2021

Document Number:

700703530**FIELD INSPECTION FORM**Loc ID 334607 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211089	WELL	PR	07/14/1994	GW	045-06847	SHAEFFER 12-6	PR
266193	WELL	PR	11/08/2003	GW	045-09124	SHAEFFER 12-6D (F12)	PR
266195	WELL	TA	07/24/2013	GW	045-09126	SHAEFFER 12-6A (F12)	TA

General Comment:**COGCC Inspection Report Summary**

On Monday 11/15/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus F12, at Location # 334607 in Garfield county Colorado.

While there, I observed well was shut in. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Vertical unit separators includes 2 glycol storage tank, storage vessel contains no labeling to specify capacity or chemical hazard information.
 2. Lack of battery signage
 3. Load lines missing caps/bull plugs
 4. Random debris around location
 5. Staining between tanks appears to have been partially removed.
 6. Chemical tank lacking legible labeling.
 7. Well head signs on the ground
- Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	CONTAINERS			
Comment:	Chemical tank lacking legible labeling.			
Corrective Action:	Provide proper labeling			Date: 12/03/2021
Type	OTHER			
Comment:	Vertical unit separators includes 2 glycol storage tank, storage vessel contains no labeling to specify capacity or chemical hazard information.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Some well head signs on the ground			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:	Lack of battery signage			
Corrective Action:	Comply with rule 605.e			Date: 12/16/2021
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Staining between tanks appears to have been partially removed.			
Corrective Action:	Remove all stained material			Date: 12/16/2021
Type	DEBRIS			
Comment:	Random debris around location			
Corrective Action:	Remove debris			Date: 12/03/2021
Type	OTHER			
Comment:	Load lines missing caps/bull plugs			
Corrective Action:	Comply with rule 603.i.			Date: 12/03/2021
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Vertical Heated Separator	# 5		corrective date
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 1		
Comment: Unmarked dead man			
Corrective Action: Mark or remove dead man			Date: 12/03/2021
Type: Ancillary equipment	# 1		
Comment: Chemical tank in plastic containment			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					

Corrective Action:		Date:	
Paint			
Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			
Berms			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Metal	Adequate	Walls Sufficient	Base Sufficient
Comment:			
Corrective Action:		Date:	
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 211089 Type: WELL API Number: 045-06847 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 266193 Type: WELL API Number: 045-09124 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 266195 Type: WELL API Number: 045-09126 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Last MIT done 8/7/2018

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Ditches				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703534	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5581937