

Inspection Photos
Operator: Simcoe
API: 067-07853
Date: 11/11/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing largely with crested wheatgrass, smooth brome, and sand dropseed.



Photo 3. View of the northern project area facing westward from the northeastern corner.



Photo 4. View of straw wattles full of sediment in the northwestern project area. Inset shows erosion downstream from wattles where additional stabilization is needed.



Photo 5. View of the reference area comprised of open pinyon and juniper woodland, with understory of gambel oak, western wheatgrass, sagebrush, and threadleaf sunflower.