

# Inspection Photos

API: 071-07766

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/12/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07766 | Date: 11/12/2021

## Inspection Photos



**Photo 1.** Facing northeast along the access road. The erosion along the road has been graded and repaired..



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07766 | Date: 11/12/2021

## Inspection Photos



**Photo 2.** The grading created has pushed dirt into a row which blocks stormwater from flowing toward the culvert shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07766 | Date: 11/12/2021

## Inspection Photos



**Photo 3.** There is a culvert shown at the red arrow which is filled in with sediment.



**Photo 4.** The culvert outlet needs to be cleaned out.



## Inspection Photos



**Photo 5.** Facing northwest toward road turns down the hill side into the canyon. The culverts have been cleaned out. There is gravel along this portion of the road but further down the road gravel was not observed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07766 | Date: 11/12/2021

## Inspection Photos



**Photo 6.** The road was graded down to the canyon bottom and erosion was repaired however there is no insufficient stabilization of the road and road side. There is no gravel along this steep portion of the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07766 | Date: 11/12/2021

## Inspection Photos



**Photo 7.** The erosion along the road side was filled but is not stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07766 | Date: 11/12/2021

## Inspection Photos



**Photo 8.** Standing at where road turns at the bottom of the canyon. Disturbed soils have not been seeded and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07766 | Date: 11/12/2021

## Inspection Photos



**Photo 9&10.** Facing east along the access road. The road was graded which created additional disturbance of the road. The photo on the right is the same area of erosion which could have been repaired with hand tools to avoid disturbance.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07766 | Date: 11/12/2021

## Inspection Photos



**Photo 11.** Facing east along the access road. Grading of the road has pushed soil into a row which needs to be raked/leveled out.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07766 | Date: 11/12/2021

## Inspection Photos



**Photo 12.** Facing southwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07766 | Date: 11/12/2021