

Inspection Photos
Operator: Simcoe
API: 067-07124
Date: 11/11/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing largely with western wheatgrass, black sagebrush, and sand dropseed.



Photo 3. View of stormwater controls installed within the western project area. Additional stabilization is needed in the northwestern portion of the project area where erosion continues around rock check.



Photo 4. View of the northern project area from the northwestern corner facing eastward.



Photo 5. View of the reference area comprised of black sagebrush shrubland with western wheatgrass, purple threeawn, and penstemons in the understory.