

Inspection Photos  
Operator: Simcoe  
API: 067-08704  
Date: 11/11/2021



Photo 1. View of the project area from the well pad entrance facing center.





Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation appears to be progressing in an early and grazed vegetative condition. Hay mulch from seeding remains in place.





Photo 3. View of the eastern project area from the southeastern corner, facing northward.





Photo 4. View of the reference area comprised of sagebrush shrubland with western wheatgrass, blue grama, snakeweed, in the understory.