

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/18/2021

Submitted Date:

11/18/2021

Document Number:

699304507**FIELD INSPECTION FORM**Loc ID 318036 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10711Name of Operator: PAINTED PEGASUS PETROLEUM LLCAddress: 16820 BARKER SPRINGS RD #521City: HOUSTON State: TX Zip: 77084**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
-
- 2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hoffman, John		john@p3petro.com	
Hubbard, Keith		khubbard@p3petro.com	
Mustacchia, Joey		jmustacchia@p3petro.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240475	WELL	SI	08/01/2021	GW	123-08263	SARGENT FARMS 2-B	SI

General Comment:

Location

Lease Road:			
Type	Access		
comment:	location is in a cornfield		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	dead weeds throughout tank battery location.		
Corrective Action:	Comply with Rule 606	Date:	12/02/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	fabricated steel pipe		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	automation		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	card in meter house indicates that calibration is current		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead inaccessible or not visible		

Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)		Date:	11/28/2021
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:			Date:	
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	shares containment with crude tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		40.109460,-104.376690
Comment:					

Corrective Action:		Date:		
--------------------	--	-------	--	--

Paint

Condition	Adequate			
Other (Content)				
Other (Capacity)	210 bbl			
Other (Type)				

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:	Date:			

Wells Served By Facilities Above

API Number	API Number	AirsID
123-08263		
123-05046		

AirsID

Venting:

Yes/No	NO		
Comment:			
Corrective Action:	Date:		

Flaring:

Type			
Comment:			
Corrective Action:	Date:		

Inspected FacilitiesFacility ID: 240475 Type: WELL API Number: 123-08263 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 06/25/2020Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: _____

End Surf Csg Pressure: 0Comment: Submit test results to the COGCC

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 11/18/2021 at approximately 1510 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Painted Pegasus LLC location: Sargent Farms B-2 at API#05-123-08263 in Weld County Colorado. Follow up to Doc # 699303868.</p> <p>While there, I observed wellsite & tank battery. SI at time of inspection.</p> <p>During this inspection the following compliance issue was observed and is now delinquent: 606 housekeeping: dead weeds throughout tank battery location, CA date 12-2-2021. 419.a.(1),(2) Bradenhead: Bradenhead inaccessible or not visible, CA date 12-2-2021</p> <p>See attached photos.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	11/18/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304508	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5584867