

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/11/2021

Submitted Date:

11/11/2021

Document Number:

699503339**FIELD INSPECTION FORM**Loc ID 319943 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 70385Name of Operator: SMITH ENERGY CORPAddress: 12706 SHILOH RDCity: GREELEY State: CO Zip: 80631**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**15 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Glenn	(970) 381-6253	gsmithten@what-wire.com	<a href="#">All Inspections</a>
Smith, Chris	(303) 709-6157/ (970) 799-3899	smithenergy@live.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201961	WELL	SI	06/01/2018	GW	001-07365	ROBIN LYNN 1	SI

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	Unable to inspect signage on site due to weed growth on location		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds unmanaged on location		
Corrective Action:	Comply with COGCC housekeeping rules	Date:	12/11/2020
Type	OTHER		
Comment:	Berms on location need to be repaired.		
Corrective Action:	on: Inadequate berms around tank(s) Repair or install berms or other secondary containment devices per Rule 605.a.(4). Corrective Action Date 12/11/2020 days. See attached photos	Date:	12/11/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	Unable to inspect due to weed growth on location		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Marked with steel fence post		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	PBV STEEL		,
Comment:	210 BBL				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	Open Top		,
Comment:	Netting adequate				
Corrective Action:					Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	200 BBLS	STEEL AST		,
Comment:	210 BBL				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Unable to inspect due to weed growth, corrective action from previous inspection				
Corrective Action:				Date:	
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 201961 Type: WELL API Number: 001-07365 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Well has been shut in since 6/1/18, missing production logs from 10/1/19 to present. Well is in need of mechanical integrity test. Contact COGCC engineering.

Corrective Action: Comply with COGCC MIT rules for shut in wells.

Date: 11/10/2021

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: No bradenhead test is on file. Bradenhead test is delinquent. Contact COGCC engineering. Provide monthly monitoring data.

11/21/2021

Corrective Action: Comply with COGCC annual bradenhead testing rules.

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 11/10/21 at approximately 1430 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Robin Lynn 1</p> <p>Company Name- Smith Energy Corp</p> <p>API- 05-001-07365</p> <p>In Adams County Colorado.</p> <p>While there, I observed SI well</p> <p>This is a follow up inspection from document # 700900331 Corrective Actions are Delinquent</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>No bradenhead test is on file. Bradenhead test is delinquent. Contact COGCC engineering. Provide monthly monitoring data.</p> <p>Comply with COGCC annual bradenhead testing rules. 11/21/21</p> <p>Well has been shut in since 6/1/18, missing production logs from 10/1/19 to present. Well is in need of mechanical integrity test. Contact COGCC engineering.</p> <p>Comply with COGCC MIT rules for shut in wells. 11/10/21</p> <p>Berms on location need to be repaired.</p> <p>on: Inadequate berms around tank(s) Repair or install berms or other secondary containment devices per Rule 605.a.(4). Corrective Action Date 12/11/2020 days. See attached photos</p> <p>Weeds unmanaged on location</p> <p>Comply with COGCC housekeeping rules 12/11/20</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	11/11/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402869024	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5579162">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5579162</a>
699503340	Inspection pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5579156">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5579156</a>