

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/10/2021

Submitted Date:

11/12/2021

Document Number:

701003918

FIELD INSPECTION FORM

Loc ID 320983 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10626
Name of Operator: DOVER ATWOOD CORPORATION
Address: 1875 HARSH AVENUE SE
City: MASSILLON State: OH Zip: 44646

Findings:

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|------------------------|----------------------------------|
| Levengood, John | (330) 809-0630 | jlevengood07@gmail.com | BACA Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 205672 | WELL | PR | 01/01/2017 | GW | 009-06083 | VILLERS, V 1-30 | PR |

General Comment:

[Routine Inspection](#)

| Location | | | |
|--|---|--------|------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Trail through farm ground | | |
| Corrective Action | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Stickers and stencils on water tank are peeling off and need replaced | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | | Date: 12/10/2021 |
| Type | WELLHEAD | | |
| Comment: | Lease sign mounted to meter run door | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | OTHER | | |
| Comment: | Meter run covering needs to be fixed | | |
| Corrective Action: | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Wire panels around unit and wellhead | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Pump Jack | # 1 | | corrective date |
| Comment: | Lufkin unit | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Prime Mover | # 1 | | |
| Comment: | Arrow gas engine | | |

| | |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------------|---|----------|----------|---------|-----------------------|
| PRODUCED WATER | 1 | 200 BBLs | Open Top | | 37.318580,-102.302410 |

Comment: Fiberglass open top water tank. Tank is empty and not in use at time of inspection. Remove tank from location or install berms

| | |
|--|-------------------------|
| Corrective Action: Comply with Rule 606 | Date: <u>12/10/2021</u> |
|--|-------------------------|

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | |
|--------------------|-------|
| Yes/No | |
| Comment: | |
| Corrective Action: | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 205672 Type: WELL API Number: 009-06083 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Other | Pass | | | |

Comment: [Access is farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402869264 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5579359 |
| 701003949 | location photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5579352 |