

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Barbed Wire		
Corrective Action:			Date:
Type	PIT		
Comment:	Barbed Wire		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Barbed Wire		
Corrective Action:			Date:

Equipment:			corrective date
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.625760,-104.102490
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 467686 Type: Location API Number: - Status: AC Insp. Status: AC

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI - Tank Battery Shut-In at the time of this Inspection

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: 40.625790 Long: -104.101760

Reference Point: SE Other: _____ Length: 20 Width: 15

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: Mesh Netting Condition: Good

Comment:

Corrective Action

Date: _____

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

COGCC Comments

Comment	User	Date
Routine Field Inspection	petrie	11/19/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696303786	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5586152