

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/18/2021

Submitted Date:

11/19/2021

Document Number:

690100019

FIELD INSPECTION FORM

Loc ID 320291 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 370 17TH STREET SUITE 5200
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		COGCCInspections@extracti onog.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203372	WELL	SI	03/01/2021	GW	001-08881	BYDALEK 2-11	EG

General Comment:

[COGCC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 203372 Type: WELL API Number: 001-08881 Status: SI Insp. Status: EG

Flowline

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: COGCC Inspector met with EOG contract personnel (Moon) on location. Well (Bydalek 2-11) has been plugged and abandoned; cut and cap work is completed. COGCC form 42 notice of start of plugging operations doc #402838917 received 10/12/2021. All on location flowlines (wellhead, dump, process) have been removed; No flowline risers were observed at the (PA) wellhead or facility areas during this field inspection. The facility/ battery has been decommissioned; associated tanks and equipment removed. Excavation/ remediation work in response to the historical release is in progress.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #402873260 received on 11/17/2021: While removing flowline at the Bydalek #2-11 (Location ID: 320291), historical suspected soil impacts were observed at the separator end flowline riser. Note: Out of service gas gathering riser (XTR Midstream) on location.	maclarej	11/19/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100020	Signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5586330
690100021	Excavation at separator area; OOS gathering riser	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5586331