

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/17/2021

Submitted Date:

11/20/2021

Document Number:

688311613**FIELD INSPECTION FORM**Loc ID 316910 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10690Name of Operator: IMPETRO RESOURCES LLCAddress: 2820 LOGAN DRIVECity: LOVELAND State: CO Zip: 80538**Status Summary:**☒ THIS IS A FOLLOW UP INSPECTION☐ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gibson, Rick	970-768-6880	rtgibson01@msn.com	
Bradley, Sam	970-593-8626	sbradley.impetro@gmail.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
233127	WELL	PR	11/01/2018	OW	121-05150	LOUDDER 14-7 2	PR

General Comment:

Reinspection >1yr

Oil in buoy area of pit, inspector left message with operator on 11/17/2021.

Inspected Facilities									
Facility ID:	233127	Type:	WELL	API Number:	121-05150	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	pr								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: YES2+ feet Freeboard: Comment: Free oil in buoy area of pit (see attached photo).Corrective Action: Remove oil from pit per Rule 909.e.Date: 11/23/2021**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688311647	IMPETRO Loudder 14-7 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5586743