

Inspection Photos

API: 071-06141

Operator: OGRIS OPERATING LLC

Inspection Date: 11/19/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 11/19/2021

Inspection Photos



Photo 1. The culverts along the road have been cleaned out and repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 11/19/2021

Inspection Photos



Photo 2. The culvert has been cleaned out. There is sediment piled around the culvert which needs to be reseeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 11/19/2021

Inspection Photos



Photo 3. Facing west at the switch back of the road where there was vehicle rutting. The road was graded however, the road was not stabilized and vehicle rutting may occur during wet winter condition.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 11/19/2021

Inspection Photos



Photo 4. The erosion gully at the second switchback of the road has been reaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 11/19/2021

Inspection Photos



Photo 5. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 11/19/2021

Inspection Photos



Photo 6. The lid on the culvert needs to be installed to prevent wildlife entry.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 11/19/2021