

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/16/2021

Submitted Date:

11/22/2021

Document Number:

688801030

FIELD INSPECTION FORMLoc ID 306757 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		sjninspections@ikavenergy.com	All Inspections
Murray, Richard		g.richard.murray@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214606	WELL	PA	01/25/1979	GW	067-06210	UTE INDIAN 5A	EI
263129	WELL	PR	11/03/2015	GW	067-08707	FC LEIDY 001 2	EI

General Comment:

On November 16, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Simcoe LLC Leidy 001 #2. For the most recent field inspection report of this facility, please refer to document #693903857. COGCC Western Integrity Inspector Richard Murray was on site during this inspection. An open excavation, associated with REM #20366, was observed in the southwest corner of the location during this inspection.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	Free standing sign near PBV has capacity listed as 95 bbl. (This sign could go over to the Leidy Barnes A #1.) Sticker on secondary containment ring is peeling off.			
Corrective Action:				Date:
Type	OTHER			
Comment:	PA marker for 067-06210.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Free standing sign near entrance to location.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted on location signs.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Stock panel enclosure around pump jack and well head.			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Stock panel enclosure around separator, meter shack, telemetry equipment, and PBV.			
Corrective Action:				Date:
Type	OTHER			
Comment:	Orange safety fencing around open excavation in southwest corner of location.			
Corrective Action:				Date:
Equipment:				
Type: Pump Jack	# 1			corrective date
Comment:				
Corrective Action:				Date:

Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor.		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLs	PBV STEEL		37.135825,-107.811849	
Comment:						
Corrective Action:						Date:

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)	21 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Wells Served By Facilities Above**AirsID**

API Number	API Number	AirsID
067-08707		

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>214606</u>	Type:	<u>WELL</u>	API Number:	<u>067-06210</u>	Status:	<u>PA</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>263129</u>	Type:	<u>WELL</u>	API Number:	<u>067-08707</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>

--

Environmental	
Spill/Remediation:	
Comment:	Open excavation in the southwest corner of the location is part of the REM #20366 flowline abandonment.
Corrective Action:	<div></div> <div>Date: <div></div></div>
Emission Control Burner (ECB): <div></div>	
Comment:	<div></div>
Pilot: <div></div>	Wildlife Protection Devices (fired vessels): <div></div>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Culverts	Pass					
Gravel	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On November 16, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Simcoe LLC Leidy 001 #2. For the most recent field inspection report of this facility, please refer to document #693903857. COGCC Western Integrity Inspector Richard Murray was on site during this inspection. An open excavation, associated with REM #20366, was observed in the southwest corner of the location during this inspection. The free standing sign near the PBV lists the capacity as 95 bbl., which is inaccurate. The sticker on the secondary containment ring is peeling off.	hughesjo	11/22/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688801031	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5587758