

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/08/2021

Submitted Date:

11/16/2021

Document Number:

701102183

**FIELD INSPECTION FORM**Loc ID 314822 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10654

Name of Operator: LASSO OIL &amp; GAS LLC

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Boulger, Levin	970-509-0256	lboulger@31operating.com	
Freeman, Kris	(254) 717-0435	kfreeman@31operating.com	
Thompson, Bud		BLThomps@BLM.gov	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229665	WELL	PR	09/01/2019	GW	103-07322	FEDERAL 2-34	PR

**General Comment:**

COGCC Follow Up Inspection Report Summary

Follow up to 05/24/2021 inspection # 701500864

Uncorrected action item(s)

• Most recent meter calibration on 6-20-2019.

• Bradenhead access is not present.

• Stormwater is flowing across the filled location ditch and over the berm. Then over the location and off the other side of the location.

Sediment is also choking the vegetation on location.

During this inspection the following compliance issues were observed:

• Dead weed debris on location.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	911
Corrective Action:	
Date:	

<b>Good Housekeeping:</b>		
Type	DEBRIS	
Comment:	Dead weed debris on location.	
Corrective Action:	Comply with Rule 606	Date: 12/03/2021

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>		
Type	PIT	
Comment:		
Corrective Action:		Date:

<b>Equipment:</b>			corrective date
Type: Bradenhead	#		
Comment:	Bradenhead access is not present.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).		Date: 02/01/2021
Type: Gas Meter Run	# 1		
Comment:	Most recent meter calibration on 6-20-2019.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date: 02/01/2021
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

<b>Venting:</b>		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

<b>Flaring:</b>	
Type	

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	229665	Type:	WELL	API Number:	103-07322	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well Latest record of production 9-1-2021								
Corrective Action:						Date:			

--	--	--	--	--	--	--	--	--	--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Fail					
Berms	Fail					

Comment: Stormwater is flowing across the filled location ditch and over the berm. Then over the location and off the other side of the location. Sediment is also choking the vegetation on location.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 06/25/2021

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type:	Lined: <u>NO</u>	Pit ID:	Lat:	Long:
Reference Point:	Other:	Length:	Width:	

**Lining:**

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type: Wildlife

Fencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO

2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402871762	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5581898">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5581898</a>
701102214	Inspection 701102183 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5581896">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5581896</a>