

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/23/2021

Submitted Date:

11/23/2021

Document Number:

690008816**FIELD INSPECTION FORM**Loc ID 464139 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                    | Comment                         |
|--------------|-------|--------------------------|---------------------------------|
| , Oxy        |       | COGCCInspections@Oxy.com | <a href="#">All Inspections</a> |

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  |             |
| Corrective Action: |  | Date: _____ |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |              |       |  |
|--------------------|--------------|-------|--|
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |

**Equipment:**

|                                   |      |       |                 |
|-----------------------------------|------|-------|-----------------|
|                                   |      |       | corrective date |
| Type: Horizontal Separator        | # 4  |       |                 |
| Comment:                          |      |       |                 |
| Corrective Action:                |      | Date: |                 |
| Type: Horizontal Heated Separator | # 19 |       |                 |
| Comment:                          |      |       |                 |
| Corrective Action:                |      | Date: |                 |
| Type: LACT                        | # 1  |       |                 |
| Comment:                          |      |       |                 |
| Corrective Action:                |      | Date: |                 |
| Type: Emission Control Device     | # 3  |       |                 |
| Comment:                          |      |       |                 |
| Corrective Action:                |      | Date: |                 |

**Tanks and Berms:**

|                |   |          |           |         |                       |
|----------------|---|----------|-----------|---------|-----------------------|
| Contents       | # | Capacity | Type      | Tank ID | SE GPS                |
| PRODUCED WATER | 3 | OTHER    | STEEL AST |         | 40.181400,-105.008410 |
| Comment:       |   |          |           |         |                       |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 286 Bbl  |  |
| Other (Type)     |          |  |

Berms

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

|                    |   |          |           |         |                       |
|--------------------|---|----------|-----------|---------|-----------------------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
| PRODUCED WATER     | 3 | OTHER    | STEEL AST |         | 40.181030,-105.009360 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

Venting:

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

Flaring:

|                    |                   |       |
|--------------------|-------------------|-------|
| Type               | Ignitor/Combustor |       |
| Comment:           |                   |       |
| Corrective Action: |                   | Date: |

**COGCC Comments**

| Comment                                     | User     | Date       |
|---|----------|------------|
| <a href="#">Routine battery inspection.</a> | carlilec | 11/23/2021 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 690008817    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588417">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588417</a> |