

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/22/2021

Submitted Date:

11/23/2021

Document Number:

690100025

FIELD INSPECTION FORM
 Loc ID 329626 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10391

Name of Operator: STONEHAM PRODUCTION LLC

Address: 5945 ZINNIA COURT

City: ARVADA State: CO Zip: 80004

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Petrie, Erica		erica.petrie@state.co.us	
Whittington, Ellice		ellice.whittington@state.co.us	
,		rbarton@sterlingenergy.us	Sterling Energy

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249818	WELL	PR	06/01/2021	GW	123-17621	CRAIG 3	SI

General Comment:

COGCC Engineering Integrity Inspection; Flowline Inspection. The Corrective Actions identified during this field inspection are located in the flowline section of report. Photos uploaded can be accessed via link(s) at end of report.

Inspected Facilities

Facility ID: 249818 Type: WELL API Number: 123-17621 Status: PR Insp. Status: SI

Flowline

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: This well is currently shut in.
 The off location flowline (wellhead line) runs approximately 950' E-NE from the Craig #3 wellhead to the facility/ tank battery (at approx. 40.718610, -103.663070) servicing the Craig 2 & 3 wells. The off location flowline registration (COGCC form 44) is currently in draft status; Operator has not submitted GIS data.

Corrective Action: Comply with COGCC rule 1101.b. Off-Location Flowline Registration;
 Note: (partial rule description)
 1101.b.(3) For off-location flowlines in existence prior to May 1, 2018, and already registered with the Commission, operators must submit, on or before December 1, 2020, a Flowline Report, Form 44, that includes:
 C. Geographic Information System (GIS) data that includes the flowline alignment and the following attributes: fluid type, pipe material type, and pipe size. GIS data must be submitted in the North American Datum of 1983 (NAD 83) and in a format approved by the Director. The GIS data for these off-location flowlines must be the most accurate data possible without using invasive methods and a minimum horizontal positional accuracy of +/- 25 feet.

Date: 12/01/2020

COGCC Comments

Comment	User	Date
The corrective action outlined on COGCC FIR Doc #696303115 submitted on 04/06/2021 is still applicable; Complete and Submit Form 17 for Annual Bradenhead Test per Rule 419.c. (5/07/2021)	maclarej	11/23/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100026	Well and signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588572
690100031	View E from wellhead to battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588573
690100032	View W from vertical treater to well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588574