

Inspection Photos
Location Name: Southern Ute #5-7
API: 05-067-08483



Southern Ute #5-7 location photo. Erosion evident along access road.



Erosional channels present along northern edge of location.

Inspection Photos
Location Name: Southern Ute #5-7
API: 05-067-08483



Southern Ute #5-7 well head. Well head and surrounding area are stained and wet.



Pump jack skid and surrounding area are wet and stained.

Inspection Photos
Location Name: Southern Ute #5-7
API: 05-067-08483



Wet and stained area near drop out tank.



Audible leak from valve in separator shack during this inspection.