

Inspection Photos
Location Name: Amoco Energy Smits Unit C1
Location ID: 311287



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Amoco Energy Smits Unit C1
Location ID: 311287



Photo 3 Pump Jack



Photo 4 ancillary equipment

Inspection Photos
Location Name: Amoco Energy Smits Unit C1
Location ID: 311287



Photo 5 TB sign

Photo 6 TB

Inspection Photos
Location Name: Amoco Energy Smits Unit C1
Location ID: 311287



Photo 7 Gas Meter Run




Photo 8 Stained soil by Gas Meter Run Flow line

Inspection Photos
Location Name: Amoco Energy Smits Unit C1
Location ID: 311287



Photo 9 Dead thistle inside and on TB berm



Photo 10 Stained soil on north side of crude tank by the Flow line

Inspection Photos
Location Name: Amoco Energy Smits Unit C1
Location ID: 311287



Photo 11 flow line manifold and aux. pump



Photo 12 Horiz. Heated Sep.