

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/18/2021

Submitted Date:

11/23/2021

Document Number:

688801042

FIELD INSPECTION FORM

Loc ID 428734 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 7650
Name of Operator: BENSON-MONTIN-GREER DRILLING CORPORATION
Address: 4900 COLLEGE BLVD
City: FARMINGTON State: NM Zip: 87402

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 9 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Stradling, Zak	(505) 324-5074	zstradling@bmgdrilling.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
115777	PIT				-	JACQUES 2	EI
214688	WELL	PR	10/01/2020	GW	067-06292	JACQUES 2	EI

General Comment:

On November 18, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Benson-Montin-Greer Jacques #2. For the most recent field inspection report of this facility, please refer to document #687904950. COGCC Western Integrity Inspector Richard Murray was on site during this inspection. The reason for this site visit was to observe work proceeding under REM #20748.

Location					
Lease Road:					
Type	Access				
comment:					
Corrective Action					Date:
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
Type	OTHER				
Comment:	La Posta Canyon CDP sign posted near entrance to location.				
Corrective Action:					Date:
Type	TANK LABELS/PLACARDS				
Comment:	Sign mounted to perimeter fencing around PBV.				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	Posted on location signs.				Date:
Corrective Action:					Date: _____
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	TANK BATTERY				
Comment:	Post and wire fencing around PBV.				
Corrective Action:					Date:
Equipment:					
					corrective date
Type: Bird Protectors	# 2				
Comment:					
Corrective Action:					Date:
Type: Horizontal Heated Separator	# 2				
Comment:	One separator near PBV and one within metal enclosure.				
Corrective Action:					Date:
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	Open Top		37.135045,-107.933630
Comment:					
Corrective Action:					Date:
Paint					

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Wells Served By Facilities Above

AirsID

API Number
067-06292

API Number	AirsID
------------	--------

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 115777 Type: PIT API Number: - Status: Insp. Status: EI

Facility ID: 214688 Type: WELL API Number: 067-06292 Status: PR Insp. Status: EI

Environmental

Spill/Remediation:

Comment: [Work is proceeding under REM #20748 to plug well and decommission all equipment on the location. Pit Facility ID #115777, related to this facility, has an unknown status in the COGIS database.](#)

Corrective Action: [The operator will submit a Form 27 Site Investigation and Remediation Workplan, required by Rule 913.c, for closure of Pit Facility ID #115777.](#)

Date: 12/23/2021

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					

Comment: [The operator will submit a Form 27 for closure of Pit Facility ID #115777 as required by Rule 913.c.](#)

Corrective Action: _____ Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: 115777 Lat: 37.134847 Long: -107.932730

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____
 Corrective _____ Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____
 Corrective _____ Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____
 Corrective _____ Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: _____
 Corrective _____ Date: _____

COGCC Comments

Comment	User	Date
<p>On November 18, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Benson-Montin-Greer Jacques #2. For the most recent field inspection report of this facility, please refer to document #687904950. COGCC Western Integrity Inspector Richard Murray was on site during this inspection. The reason for this site visit was to observe work proceeding under REM #20748. The Jacques #2 well head has been cut off and a PA marker has been welded onto the casing. The flow lines have been marked with pin flags. Flow lines will be abandoned and removed. The La Posta Canyon CDP shares this location.</p>	hughesjo	11/23/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688801043	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588764