

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/16/2021

Submitted Date:

11/17/2021

Document Number:

701102217

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
314990 \_\_\_\_\_ LONGWORTH, MIKE \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 74290  
Name of Operator: RETAMCO OPERATING INC  
Address: PO BOX 790  
City: RED LODGE State: MT Zip: 59068

**Findings:**

- 8 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Gose, Tom	210-216-0819	tomgose@retamco.com	
Glennon, Joe	406-446-1568	joeglennon@retamco.com	
Thompson, Bud		BLThomps@BLM.gov	
Heil, John		john.heil@state.co.us	
Johnson, Joe	406-446-1568	joejohnson@retamco.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230045	WELL	PR	06/01/2021	GW	103-07704	PHILADELPHIA CREEK 1	PR

**General Comment:**

COGCC Follow Up Inspection Report Summary  
Follow up to 9/7/2021 inspection # 701101923 and 11/10/2021 inspection # 701102195  
Uncorrected action item(s)  
• No battery sign at tank battery.  
Corrected action item(s)  
• Tank capacity has been filled in on tank label.  
• Dead weed debris have been cleared from location.  
• Tank has been lifted for repair and inspection. Stained materials collected in blue polly drums.  
During this inspection the following compliance issues were observed:  
• Tank labeled WATER with NFPA diamond RED 4 BLUE 2 YELLOW 1 , Spilled hydrocarbon fluid on tank berm floor from tank.  
Contents posted as "Water" Water is not a proper content name for fluids recovered from down hole of well.  
• Tank has been lifted for repair and inspection. Inspect, maintain and repair tanks to comply with rule 609.b.  
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Tank labeled WATER with NFPA diamond RED 4 BLUE 2 YELLOW 1 , Spilled hydrocarbon fluid on tank berm floor from tank. Contents posted as "Water" Water is not a proper content name for fluids recovered from down hole of well.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	02/25/2022
Type	BATTERY		
Comment:	No battery sign at tank battery.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	12/10/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank capacity has been filled in on tank label.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PIT		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
	1	<100 BBLS	STEEL AST		,
Comment:	Tank has been lifted for repair and inspection.				
Corrective Action:	Inspect, maintain and repair tanks to comply with rule 609.b.				Date: 12/18/2021

**Paint**

Condition	
Other (Content)	
Other (Capacity)	72 bbl

Other (Type) _____				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Tank has been lifted for repair and inspection. Stained materials collected in blue polly drums.			
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 230045 Type: WELL API Number: 103-07704 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402873227	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5583133">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5583133</a>
701102221	Inspection 701102217 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5583131">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5583131</a>