

# Inspection Photos

API: 071-09244

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/12/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09244 | Date: 11/12/2021

## Inspection Photos



**Photo 1.** Facing northwest along the access road which has not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09244 | Date: 11/12/2021

## Inspection Photos



**Photo 2.** Facing northwest along the access road which has not been reclaimed. There are signs of erosion as the road ascends to the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09244 | Date: 11/12/2021

## Inspection Photos



**Photo 3.** Facing northwest toward the location. The location has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09244 | Date: 11/12/2021

## Inspection Photos



**Photo 4.** Facing west at the location. The soils are not stabilized and there are signs of erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09244 | Date: 11/12/2021

## Inspection Photos



**Photo 5.** Facing toward the northwest cutslope. There is a noxious weed shown at red arrow (Plumeless thistle).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09244 | Date: 11/12/2021

## Inspection Photos



**Photo 6.** Facing southeast toward the fill slope. There is a noxious weed shown at red arrow (Plumeless thistle).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09244 | Date: 11/12/2021

## Inspection Photos



**Photo 7.** Drone aerial photo facing north toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09244 | Date: 11/12/2021

## Inspection Photos



**Photo 8.** Drone aerial photo facing northeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09244 | Date: 11/12/2021

## Inspection Photos



**Photo 9.** Facing down toward the fill slope. There are signs of rilling erosion along the fill slope of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09244 | Date: 11/12/2021

## Inspection Photos



**Photo 10.** Drone aerial photo facing northwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09244 | Date: 11/12/2021

## Inspection Photos



**Photo 11.** Drone aerial photo facing west toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09244 | Date: 11/12/2021