

Inspection Photos

Location Name: CAERUS PICEANCE LLC CASS-GARBER-68S96W /1NWNE

Location ID: 334129



Photo #5236 from entrance to location.



Photo #5237 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC CASS-GARBER-68S96W /1NWNE

Location ID: 334129



Photo #5238 Location lacks stabilization.



Photo #4806 from inspection #699803561 conducted on 8/16/21.

Inspection Photos

Location Name: CAERUS PICEANCE LLC CASS-GARBER-68S96W /1NWNE

Location ID: 334129



Photo #5239 location lacks stabilization.



Photo #5240 No form of tracking BMP located at entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC CASS-GARBER-68S96W /1NWNE

Location ID: 334129



Photo #4807 from inspection #699803561 conducted on 8/16/21.