

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/17/2021

Submitted Date:

11/24/2021

Document Number:

693200846**FIELD INSPECTION FORM**Loc ID 325776 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------------|-------|-------------------------------|----------------------------------|
| Hughes, Jim | | jimo.hughes@state.co.us | |
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | Engineering Integrity Supervisor |
| , General | | sjninspections@ikavenergy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 215364 | WELL | PR | 08/31/2021 | GW | 067-06969 | BARNES-LEIDY A 1 | PR |

General Comment:

Engineering Integrity Inspection performed on November 17, 2021, to witness Plug and Abandonment of flowlines and no abandoned risers were left on location

COGCC joint inspection with EPS J. Huges and Western Integrity Inspector R. Murray

Inspected Facilities

Facility ID: 215364 Type: WELL API Number: 067-06969 Status: PR Insp. Status: PR

Flowline

| | | |
|----|-----------------|------------|
| #1 | Type: Dump Line | 1 of Lines |
|----|-----------------|------------|

Flowline Description

Flowline Type: Dump Line Size: 6" Material: Fiberglass
 Variance: No Age: 5-10 Yrs Contents: Produced Water

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Improper abandonment of off-location flowlines. Flowlines were cut and left open ended with no caps installed. Open to ground water and environment. Flowlines were cut on location 3' below grade at the separator riser and at the tie-in of the new flowline. The Abandonment process has been started and should be finished per 1105 Rules. If this best practice was used on other locations we would want this corrected as well.

Corrective Action: Complete flowline abandonments to comply with Rule 1105.

Date: 12/06/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 693200847 | Photo 2 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5589478 |
| 693200848 | Photo 1 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5589479 |