

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/22/2021

Submitted Date:

11/24/2021

Document Number:

700703565

**FIELD INSPECTION FORM**Loc ID 314833 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 200502

Name of Operator: 31 OPERATING

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Thomson, Bud		BLThomps@BLM.gov	
, COGCC		dnr_cogccengineering@state.co.us	engineering
, COGCC		kelly.rosenberg@state.co.us	regulatory/hearings
operating, 31		kfreeman@31operating.com	
, COGCC		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229692	WELL	SI	10/01/2020	GW	103-07349	FEDERAL 1	SI

**General Comment:****COGCC Inspection Report Summary**

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

On Monday 11/22/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at 31 Operating Federal 1, at Location # 314833 in Rio Blanco county Colorado.

While there, I observed no production operations and labeling on location/meter house have a different operator (KT Resources). Emergency phone # has also been changed, I contacted the emergency contact without fail (KT Resources). Wells are shut in. All meters have been not calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. There is no evidence of tracking pad at time of inspection.

During this inspection the following compliance issues were observed:

1. Access road shows signs of lack of stabilization/compaction.
2. Locations weeds have turned into debris throughout location.
3. Lack of tank battery signage.
4. No evidence of tracking control BMP's.
5. Location signs are incorrect.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	See stormwater			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	OTHER			
Comment:	Location signs are incorrect.			
Corrective Action:	Provide proper signage			Date: 12/31/2021
Type	BATTERY			
Comment:	Lack of battery signage			
Corrective Action:	Comply with rule 605.e			Date: 12/31/2021
Emergency Contact Number:				
Comment:	1800-288-0560/911			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	DEBRIS			
Comment:	Locations weeds have turned into debris throughout location.			
Corrective Action:	Remove all debris			Date: 12/31/2021
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Equipment:</b>				
Type: Bird Protectors	# 2			corrective date
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	No visible Braden head access.			
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)			Date: 12/10/2021

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Well head not on plunger lift		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	HEATED STEEL AST		,	
Comment:	Tank is empty					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 229692 Type: WELL API Number: 103-07349 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last produced 6/2020

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Fail			

Comment: [1. Access road shows signs of lack of stabilization/compaction.](#)  
[2. No evidence of tracking control BMP's.](#)

Corrective Action: [Install or repair required BMPs and Provide proof of tracking control BMP's](#)

Date: 12/31/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703573	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5589499">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5589499</a>