

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/22/2021

Submitted Date:

11/24/2021

Document Number:

700703568

**FIELD INSPECTION FORM**

Loc ID: 316153      Inspector Name: Ramsey, Scott      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

6 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 200502

Name of Operator: 31 OPERATING

Address: 3021 RIDGE RD #156

City: ROCKWALL      State: TX      Zip: 75032

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, COGCC		kelly.rosenberg@state.co.us	regulatory/hearings
, COGCC		dnr_cogccengineering@state.co.us	engineering
Thomson, Bud		BLThomps@BLM.gov	
operating, 31		kfreeman@31operating.com	
, COGCC		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232247	WELL	SI	10/01/2020	GW	103-09918	WRD FEDERAL 30-44	SI

**General Comment:**

[COGCC Inspection Report Summary](#)

Any Corrective Actions from previous Inspections that have not been addressed are still applicable. On Monday 11/22/2021 at approximately 1400, I, Inspector Scott Ramsey, conducted a routine inspection at 31 Operating WRD Fed 33-44, at Location # 316153 in Rio Blanco county Colorado. While there, I observed no production operations and labeling on location/meter house have a different operator (KT Resources). Emergency phone # has also been changed, I contacted the emergency contact without fail (KT Resources). Wells are shut in. All meters have been not calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. There is no evidence of tracking pad at time of inspection. During this inspection the following compliance issues were observed:

1. Access road/location in areas shows signs of lack of stabilization/compaction.
2. No evidence of tracking control BMP's.
3. Erosion channels on fill slope of location with sediment migration from pad.
4. Locations weeds have turned into debris throughout location.
5. Lack of tank battery signage.
6. Location signs are incorrect.
7. One chemical tank is not labeled.
8. No visible Braden head access.

Refer to photograph of observed compliance issue.  
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	See stormwater		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	One chemical tank is not labeled.		
Corrective Action:	Provide proper labeling		Date: 12/31/2021
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Location signs are incorrect.		
Corrective Action:	Provide proper signage		Date: 12/31/2021
Type	BATTERY		
Comment:	Lack of tank battery signage.		
Corrective Action:	Comply with rule 605.e		Date: 12/31/2021
<b>Emergency Contact Number:</b>			
Comment:	1-800-288-0560/911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Locations weeds have turned into debris throughout location.		
Corrective Action:	Remove all debris		Date: 12/31/2021
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type:	Bird Protectors	# 2	corrective date
Comment:			
Corrective Action:			Date:

Type: Ancillary equipment	# 1		
Comment:	Chemical tank in plastic containment		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Well head not on plunger lift		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	No visible Braden head access.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)		Date: 12/10/2021

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:

<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 232247 Type: WELL API Number: 103-09918 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last produced 9/2020

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail	Compaction	Fail			

Comment:   
 1. Access road/location in areas shows signs of lack of stabilization/compaction.   
 2. No evidence of tracking control BMP's.   
 3. Erosion channels on fill slope of location with sediment migration from pad.

Corrective Action: **Install or repair required BMPs and Provide proof of tracking control BMP's**

Date: 12/31/2021

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703576	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5589502">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5589502</a>