

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/18/2021

Submitted Date:

11/22/2021

Document Number:

688801032

FIELD INSPECTION FORM

Loc ID 325388 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 7650
Name of Operator: BENSON-MONTIN-GREER DRILLING CORPORATION
Address: 4900 COLLEGE BLVD
City: FARMINGTON State: NM Zip: 87402

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 8 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Stradling, Zak	(505) 324-5074	zstradling@bmgdrilling.com	
Murray, Richard		g.richard.murray@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
115780	PIT				-	LA POSTA CANYON 4	EI
214687	WELL	PR	10/01/2020	GW	067-06291	LA POSTA CANYON 4	EI

General Comment:

On November 18, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Benson-Montin-Greer La Posta Canyon #4. For the most recent field inspection report of this facility, please refer to document #693903445. COGCC Western Integrity Inspector Richard Murray was on site during this inspection. A construction crew was performing work associated with REM #20746.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	PA marker has been welded on.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	PBV sign has been removed with fencing.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Sign mounted to meter house.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER		100 BBLS			37.136768,-107.952347	
Comment:	_____					

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
067-06291

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 115780 Type: PIT API Number: - Status: Insp. Status: EI

Facility ID: 214687 Type: WELL API Number: 067-06291 Status: PR Insp. Status: EI

Environmental

Spill/Remediation:

Comment: [Work is proceeding under REM #20746 to decommission location.](#)

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: 115780 Lat: 37.138437 Long: -107.950871

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Pit Facility ID #115780, related to the La Posta Canyon #4, has an unknown status in the COGIS database.

Corrective Action: The operator will submit a Form 27 Site Investigation and Remediation Workplan, required by Rule 913.c., to close Pit Facility ID #115780.

Date: 12/22/2021

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action:

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action:

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action:

Date: _____

COGCC Comments

Comment	User	Date
<p>On November 18, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Benson-Montin-Greer La Posta Canyon #4. For the most recent field inspection report of this facility, please refer to document #693903445. COGCC Western Integrity Inspector Richard Murray was on site during this inspection. A construction crew was performing work associated with REM #20746. The PBV contained fluids and was unable to be moved at the time of this inspection. The wellhead had been cut off and a PA marker welded on. Flow lines were to be excavated and removed at a later date. Equipment from the BMG Drilling La Posta Canyon #2 was being temporarily stored on location to make room for PA operations on that location.</p>	hughesjo	11/22/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402878360	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5587931
688801033	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5587928