

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GR /23-11V

Location ID: 323872



Photo #5252 from entrance to location.



Photo #5253 from entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GR /23-11V

Location ID: 323872



Photo #5254 from entrance to location.



Photo #5255 Rill erosion occurring in access road.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GR /23-11V

Location ID: 323872



**Photo #5256 Insufficient velocity checks in ditches.**



**Photo #5257 Rill erosion occurring in access road.**