

Inspection Photos
Operator: Simcoe
API: 067-06841
Date: 11/17/2021



Photo 1. View of the project area from the southeastern corner of the working area facing center.



Photo 2. View of the southern project area from the southeastern corner facing westard. Revegetation is progressing with western wheatgrass and sand dropseed.



Photo 3. View of what appears to be surface owner cars and material stored in the western project area, needs to be removed. Site needs to be managed to prevent disposal of equipment and debris.



Photo 4. View of pile of cement debris observed within the southeastern project area.



Photo 5. View of reference area comprised of pinyon and juniper woodland with gambel oak, western wheatgrass, and mountain mahogany in the understory.