

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402786825

Date Received:
09/14/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10766
Name of Operator: ARKOMA OPERATIONS LLC
Address: 2121 S COLUMBIA AVE SUITE 101
City: TULSA State: OK Zip: 74114

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Andrew Price</u>	<u>918-965-0044</u>	<u>aprice@arkomaops.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903531
Inspection Date: 08/06/2021 FIR Submit Date: 08/13/2021 FIR Status: _____

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC Company Number: 10464
Address: 1001 17TH STREET STE 1160
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 326352

Location Name: HERRERA GAS UNIT A-N33N8W Number: 20NENW County: LA PLATA
Qtrqtr: NENW Sec: 20 Twp: 33N Range: 8W Meridian: N
Latitude: 37.093120 Longitude: -107.745160

FACILITY - API Number: 05-067-00 Facility ID: 216287

Facility Name: HERRERA GAS UNIT A Number: 4
Qtrqtr: NENW Sec: 20 Twp: 33N Range: 8W Meridian: N
Latitude: 37.093120 Longitude: -107.745160

CORRECTIVE ACTIONS:

1 CA# 154806

Corrective Action: -Gravel, fill, and sediment discharged from the project area needs to be removed and properly managed. Revegetation is required if desirable vegetative cover is damaged as a result of material discharge. Corrective action date: 9/15/2021.

Date: 09/15/2021

Response: CA COMPLETED Date of Completion: 09/10/2021

Operator Comment: Cleaned sediment from diversion ditches, Installed rock run downs and check dams. Removed rocks and gravel from the road and the sediment and gravel discharged from the project area, bare ground was roughened and reseeded.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 154807

Corrective Action: -Stormwater (ie: BMPs) and erosion controls (ie: erosion control blanket, hydromulch, etc.) need to be installed to stabilize erosion and prevent sediment discharge within the project area, no later than 9/15/2021. Controls need to be selected, sized, installed, and maintained according to good engineering practices such as those described by CDOT in their erosion control manuals.

Date: 09/15/2021

Response: CA COMPLETED

Date of Completion: 09/10/2021

Operator
Comment:

Cleaned sediment from diversion ditches, Installed rock run downs and check dams. Removed rocks and gravel from the road and the sediment and gravel discharged from the project area, bare ground was roughened and reseeded.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: _____

Title: Engineering Analyst

Date: 9/14/2021 3:16:17 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402786825	FIR RESOLUTION SUBMITTED
402811273	Herrera Gas Unit A 4 9-15-21 (693903531) remedial report

Total Attach: 2 Files