

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402786841

Date Received:

09/20/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10766

Name of Operator: ARKOMA OPERATIONS LLC

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Andrew Price

918-965-0044

aprice@arkomaops.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903556

Inspection Date: 08/12/2021

FIR Submit Date: 08/18/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC

Company Number: 10464

Address: 1001 17TH STREET STE 1160

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 326237

Location Name: JAQUES-N33N8W Number: 27NWSE County: LA PLATA

Qtrqr: NWSE Sec: 27 Twp: 33N Range: 8W Meridian: N

Latitude: 37.071771 Longitude: -107.700362

FACILITY - API Number: 05-067-00 Facility ID: 454845

Facility Name: Jaques Number: 12

Qtrqr: NWSE Sec: 27 Twp: 33N Range: 8W Meridian: N

Latitude: 37.071771 Longitude: -107.700362

CORRECTIVE ACTIONS:

1 ☒ CA# 154986

Corrective Action: -Debris was identified on the well pad and needs to be removed by 9/18/2021.

Date: 09/18/2021

Response: CA COMPLETED

Date of Completion: 09/17/2021

Operator Comment: Removed pieces of metal debris washed onto well pad.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 154987

Corrective Action: -Revegetation needs to be conducted within the interim reclamation areas (well pad cut and fill slopes).

Date: 11/12/2019

Response: CA COMPLETED

Date of Completion: 09/17/2021

Operator Comment: Mowed kochia on the fill slope.  
We will reseed the cut and fill slopes before the 11/12/21 due date.

COGCC Decision: **Not Approved**

COGCC Representative: Response demonstrates that corrective action is partially addressed.

3 ☒ CA# 154988

Corrective Action: -Stormwater and erosion controls need to be installed to stabilize erosion within the project area. Stormwater controls need to be selected, sized, installed, and maintained according to good engineering practices such as those described by CDOT in their erosion control manuals.

Date: 11/12/2019

Response: CA COMPLETED

Date of Completion: 09/17/2021

Operator Comment: Cleaned out diversion ditches, and removed sediment from the toe of the slope. Filled in rills and channels.  
Rebuilt rock run down and cleaned out outlet piping.  
Reseeded cut slope and diversion berms.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed:

Title: Engineering Analyst

Date: 9/20/2021 1:58:59 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402786841	FIR RESOLUTION SUBMITTED
402816847	Jaques 6F,10,11,12 9-18-21 (693903556) remediation

Total Attach: 2 Files