

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/23/2021

Submitted Date:

11/29/2021

Document Number:

700703579**FIELD INSPECTION FORM**Loc ID 315978 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 200502Name of Operator: 31 OPERATINGAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|-------|-----------------------------|-------------------------------------|
| Thomson, Bud | | BLThomps@BLM.gov | |
| , COGCC | | mike.leonard@state.co.us | |
| operating, 31 | | kfreeman@31operating.com | |
| , COGCC | | kelly.rosenberg@state.co.us | regulatory/hearings |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 231846 | WELL | SI | 10/01/2020 | GW | 103-09517 | MOBIL-JACOBS 1-3 | SI |

General Comment:[COGCC Inspection Report Summary](#)

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

On Tuesday 11/23/2021 at approximately 0900, I, Inspector Scott Ramsey, conducted a routine inspection at 31 Operating Mobil-Jacobs 1-3, at Location # 315978 in Rio Blanco county Colorado.

While there, I observed no production operations. Well is shut in. All meters have been not calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. There is no evidence of tracking pad at time of inspection.

During this inspection the following compliance issues were observed:

1. No evidence of tracking control BMP's.
2. Locations weeds have turned into debris throughout location.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

| | | | |
|--------------------|--------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Hard to find | | |
| Corrective Action | | Date: | |

Overall Good: ☐

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--------------------|-------|--|
| Emergency Contact Number: | | | |
| Comment: | 1-800-209-9762/911 | Date: | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--------------------------------------------------------------|-------|------------|
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | Locations weeds have turned into debris throughout location. | | |
| Corrective Action: | Remove all debris | Date: | 12/31/2021 |

Overall Good: ☐

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|-------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | Well head not on plunger lift | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 231846 Type: WELL API Number: 103-09517 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last produced 9/2020

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: 1. No evidence of tracking control BMP's.
Limited stormwater inspection due to debris (Dead weeds)

Corrective Action: Provide proof of tracking control BMP's

Date: 12/31/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 700703589 | Photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5591145 |