

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/23/2021

Submitted Date:

11/29/2021

Document Number:

700703586

FIELD INSPECTION FORMLoc ID 316194 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 200502

Name of Operator: 31 OPERATING

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, COGCC		mike.leonard@state.co.us	
, COGCC		kelly.rosenberg@state.co.us	regulatory/hearings
operating, 31		kfreeman@31operating.com	
Thomson, Bud		BLThomps@BLM.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256095	WELL	SI	10/01/2020	GW	103-09978	GOVERNMENT 4-34	SI

General Comment:**COGCC Inspection Report Summary**

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

On Tuesday 11/23/2021 at approximately 1300, I, Inspector Scott Ramsey, conducted a routine inspection at 31 Operating Gov't #4-34, at Location # 316194 in Rio Blanco county Colorado.

While there, I observed no production operations. Well is shut in. All meters have been not calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. There is no evidence of tracking pad at time of inspection.

During this inspection the following compliance issues were observed:

1. No evidence of tracking control BMP's.
2. Cut slope shows signs of lack of stabilization with vegetation roots being exposed along with riling.
3. Locations weeds have turned into debris throughout location.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	OTHER			
Comment:	One single separator unit includes one glycol storage tank, approximately 118" x 36" x 33" = 14.4 BBLS, storage vessels contain no labeling to specify capacity or chemical hazard information.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	1-800-209-9762/911			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	DEBRIS			
Comment:	Locations weeds have turned into debris throughout location.			
Corrective Action:	Remove all debris			Date: 12/31/2021
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Bradenhead	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Other	# 1			
Comment:	Well head not on plunger lift			

Corrective Action:		Date:	
<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 256095 Type: WELL API Number: 103-09978 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Last produced 9/2020

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 1. No evidence of tracking control BMP's.
2. Cut slope shows signs of lack of stabilization with vegetation roots being exposed along with riling.

Corrective Action: Provide proof of tracking control BMP's and Install or repair required BMPs

Date: 12/31/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	434295	400314860	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703593	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5591152