

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/22/2021

Submitted Date:

11/23/2021

Document Number:

690100025

**FIELD INSPECTION FORM**Loc ID 329626 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10391

Name of Operator: STONEHAM PRODUCTION LLC

Address: 5945 ZINNIA COURT

City: ARVADA State: CO Zip: 80004

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Petrie, Erica		erica.petrie@state.co.us	
,		rbarton@sterlingenergy.us	Sterling Energy
Whittington, Ellice		ellice.whittington@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249818	WELL	PR	06/01/2021	GW	123-17621	CRAIG 3	SI

**General Comment:**

COGCC Engineering Integrity Inspection; Flowline Inspection. The Corrective Actions identified during this field inspection are located in the flowline section of report. Photos uploaded can be accessed via link(s) at end of report.

**Inspected Facilities**

Facility ID: 249818 Type: WELL API Number: 123-17621 Status: PR Insp. Status: SI

**Flowline**

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: \_\_\_\_\_ Material: \_\_\_\_\_  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: This well is currently shut in.  
 The off location flowline (wellhead line) runs approximately 950' E-NE from the Craig #3 wellhead to the facility/ tank battery (at approx. 40.718610, -103.663070) servicing the Craig 2 & 3 wells. The off location flowline registration (COGCC form 44) is currently in draft status; Operator has not submitted GIS data.

Corrective Action: Comply with COGCC rule 1101.b. Off-Location Flowline Registration;  
 Note: (partial rule description)  
 1101.b.(3) For off-location flowlines in existence prior to May 1, 2018, and already registered with the Commission, operators must submit, on or before December 1, 2020, a Flowline Report, Form 44, that includes:  
 C. Geographic Information System (GIS) data that includes the flowline alignment and the following attributes: fluid type, pipe material type, and pipe size. GIS data must be submitted in the North American Datum of 1983 (NAD 83) and in a format approved by the Director. The GIS data for these off-location flowlines must be the most accurate data possible without using invasive methods and a minimum horizontal positional accuracy of +/- 25 feet.

Date: 12/01/2020

**COGCC Comments**

Comment	User	Date
The corrective action outlined on COGCC FIR Doc #696303115 submitted on 04/06/2021 is still applicable; Complete and Submit Form 17 for Annual Bradenhead Test per Rule 419.c. (5/07/2021)	maclarej	11/23/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402879056	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588575">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588575</a>
690100026	Well and signage	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588572">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588572</a>
690100031	View E from wellhead to battery	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588573">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588573</a>

690100032	View W from vertical treater to well	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588574">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588574</a>